## Mt. Blue Regional School District

129 Seamon Road Suite 2 Farmington, Maine 04938

Telephone (207) 778-6571 Fax: (207) 778-4160


October 27, 2020

Dear CCHS Parents and Staff,

I have received several questions and concerns about the ventilation system at Cape Cod Hill School. In response, our Director of Facilities, Bill Greenlaw, had the ventilation system and air exchange tested, and the airflow reviewed. The review was thorough. The good news is that the system is exchanging air at a rate that exceeds the recommendations and is functioning at full capacity.

During the fall and warmer weather days, we took extra precautions, as recommended by the Maine DOE for all schools, and opened windows and used fans to increase airflow in accordance with district protocols. Now that colder weather is upon us, we are shutting windows and currently have the air handlers operating at maximum capacity. All indoor air quality test results are considered excellent and that there is more than adequate air circulation and exchange to provide a healthy environment for our students and staff.

Please be assured that our daily protocols follow all recommendations of the Maine CDC and Maine DOE. Student and staff safety is the focus of these protocols and at the forefront of our facilities management plan. Included below is an example of the information we receive as we continually monitor the various components of the ventilation system.



Sincerely, Tina Meserve Superintendent